

<b>Kotzebue Readiness Center - Roof Replacement, Building Repair, and Fuel Tank Replacement.</b>	<b>FY2009 Request:</b>	<b>\$1,205,000</b>
	<b>Reference No:</b>	<b>45565</b>

<b>AP/AL:</b> Allocation <b>Category:</b> Public Protection <b>Location:</b> Kotzebue <b>House District:</b> Arctic (HD 40) <b>Estimated Project Dates:</b> 07/01/2008 - 06/30/2011 <b>Appropriation:</b> Military and Veterans Affairs Deferred Maintenance Projects	<b>Project Type:</b> Deferred Maintenance  <b>Contact:</b> John Cramer <b>Contact Phone:</b> (907)428-6009
--	---

**Brief Summary and Statement of Need:**  
 Deferred maintenance request for the Kotzebue Readiness Center to include roof replacement, replacement of exterior windows, boiler replacement, repair of floors, walls and ceilings, replacement of interior lighting, replacement of exterior doors, ramp replacement, replacement of above ground fuel tanks and replacement of overhead doors.

Funding:	FY2009	FY2010	FY2011	FY2012	FY2013	FY2014	Total
ASLC Bonds	\$718,100						\$718,100
Fed Rcpts	\$486,900						\$486,900
<b>Total:</b>	<b>\$1,205,000</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$1,205,000</b>

<input type="checkbox"/> State Match Required	<input type="checkbox"/> One-Time Project	<input type="checkbox"/> Phased - new	<input type="checkbox"/> Phased - underway	<input checked="" type="checkbox"/> On-Going
0% = Minimum State Match % Required		<input type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill	

<b>Operating &amp; Maintenance Costs:</b>	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	0
<b>Totals:</b>	<b>0</b>	<b>0</b>

**Additional Information / Prior Funding History:**

**Project Description/Justification:**  
 The Kotzebue Readiness Center and Aviation Operations Facility has a backlog of deferred maintenance.  
  
 Projects to be completed are roof replacement, replacement of exterior windows at lower level, replacement of boilers, repair of floors, walls and ceilings, replacement of interior lighting, replacement of exterior door, replace ramp, replacement of above the ground 3000 gallon fuel tanks, and replacement of overhead doors.